















STEP	IMAGE	DESCRIPTION
1		<p>Prior to starting the TSST SPARE NUC PC ASSY, switch the plug from I → O on the underside of the Kiosk.</p> <p>Remove the Power Lead & Network Cable.</p>
2		<p>Unlock and open the Top Door by pushing the Button on the RH side of the Top Door.</p>
3		<p>The NUC PC is in the PC Tray in the bottom of the Kiosk.</p> <p>Access to the PC Tray is from the Teller side.</p>
4		<p>Re-orientate the Teller LCD Screen upwards to the full horizontal position to allow access to the PC Tray.</p>




STEP	IMAGE	DESCRIPTION
5		<p>Remove & retain 4x Pan Head Screws fastening the PC Tray to the Main Frame using a #2 Phillips Head Screwdriver.</p>
6		<p>The PC Tray travel is limited by the Main Loom length.</p> <p>Partially pull out the PC Tray ensuring that there is suitable support under the PC Tray prior to full removal.</p>
7		<p>Disconnect all Loom plugs from the PC as shown.</p> <p>NOTE: Prior to removing the Loom Connectors from the PC, consider marking these to assist with the reconnection with the PC at the later Step.</p>

STEP	IMAGE	DESCRIPTION
8		<p>Once all PC Loom plugs are disconnected, the PC Tray can be completely removed from the Kiosk.</p>
9		<p>Place the PC Tray onto stable bench / table ensuring that the power switch is on the underside of Tray.</p> <p>The NUC PC is located on the LH side of the PC Tray as highlighted.</p>
10		<p>Remove & retain 4x M4 Wizlock Nuts from the 4x Studs on the PSU PC TRAY, using a 7mm Socket Head Drive & Handle.</p> <p>Slide the NUC PC Mount from PC Tray out of the Slots.</p> <p>Completely remove from the PC Tray.</p>

STEP	IMAGE	DESCRIPTION
11		<p>Turn over the NUC PC.</p> <p>Remove & retain the 2x M3 x 10mm Long Screws from the NUC Mount using a #2 Phillips Head Screwdriver.</p>
12		<p>Remove TSST SPARE NUC PC ASSY from packaging.</p> <p>Discard packaging.</p>
13		<p>Lay the TSST SPARE NUC PC ASSY upside down with the 4x rubber stops & 2x threaded holes facing upwards.</p> <p>Place the Mount to the TSST SPARE NUC PC ASSY and align the 4x clearance holes.</p> <p>Install the 2x M3 x 10mm Long Screws and fasten using a #2 Phillips Head Screwdriver.</p> <p>NOTE: Do not overtighten the Screws as this will distort the Mount.</p>

STEP	IMAGE	DESCRIPTION
16		<p>Install the TSST SPARE NUC PC ASSY onto the 4x Studs on the PSU PC Tray & slide to stop position.</p> <p>Re-install 4x M4 Wizlock Nuts and fasten using a 7mm Socket Head Drive & Handle.</p> <p>CHECK: Refit all connectors & ensure that the 2x Antenna Threads are facing the RH side of the PC Tray.</p>
14		<p>CAUTION: THE PC TRAY IS TO BE TESTED FOR ELECTRICAL SAFETY PRIOR TO THE RE-INSTALLATION INTO THE KIOSK.</p> <p>USE A HEAVY-DUTY SAFETY EXTENSION LEAD with IN-LINE RCD SAFETY SWITCH.</p>
15		<p>Place PC Tray onto stable bench / table ensuring access to power switch on underside of Tray.</p> <p>Instal female plug of Safety Extension Lead with In-Line RCD Safety Switch into PC Tray → switch the plug from O → I on the underside of the PC Tray.</p> <p>Fit male plug of Safety Extension Lead with In-Line RCD Safety Switch into GPO.</p> <p>Stand away from PC Tray.</p> <p>Turn switch of GPO from O → I.</p> <p>Validate that the RCD Safety Switch does not trip.</p> <p>Turn switch of GPO from I → O.</p> <p>PASS: Remove the Power Lead from PC Tray. Install into Kiosk.</p> <p>FAIL: Isolate for inspection – DO NOT INSTAL.</p>

STEP	IMAGE	DESCRIPTION
17		<p>Prepare to re-install the PC Tray back into the Kiosk.</p>
18		<p>Partially re-install the PC Tray into the 2x Slides, ensuring that there is suitable support under the PC Tray prior reconnecting of Looms.</p> <p>Reconnect all HUB IO MNT Loom plugs into the PC as shown.</p>

STEP	IMAGE	DESCRIPTION
19		<p>Gently push the PC Tray into the Kiosk</p> <p>Check: Ensure that the Looms do not catch on the PC Tray when sliding in.</p> <p>If the Looms catch, pull out the PC Tray to re-adjust the Looms.</p>
20		<p>Re-install the 4x Pan Head Screws to fasten the PC Tray into the Main Frame.</p>
21		<p>Install the Power Lead & Network Cable to the underside of the Kiosk.</p> <p>Switch the plug from O → I.</p>